

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
1		Live oak	Lost Cove Drive	20	30	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	6/26/23
2		Live oak	Lost Cove Drive	12	25	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	6/26/23
3		Live oak	Lost Cove Drive	22	25	Good	Good	Negative	Co-dominant leaders w/o included bark			Clearance Prune		Roadway clearance pruning recommended		As soon as possible	Yes	3yr Cycle	Low	Street	6/26/23
4	6291	Laurel oak	Lost Cove Drive	33	55	Good	Poor	Positive	Cavity/decay - moderate, Basal decay	Fungus		Priority 1 Removal			Ganoderma sessile Pathogenic wood decay fungus observed	Urgent	No		High	Street	6/26/23
5	6292	Live oak	Lost Cove Drive	42	55	Good	Good	Negative	Co-dominant leaders w/o included bark, Cavity/decay - small			Clearance Prune				As soon as possible	Yes	3yr Cycle	Moderate	Street	6/26/23
6		Live oak	Lost Cove Drive	18		Good	Good	Negative				Clearance Prune		Broadway clearance pruning recommended		As soon as possible	Yes	3yr Cycle	Low	Street	6/26/23
7		Southern magnolia	Lost Cove Drive	13	25	Fair	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Sparse foliage, Branch tip dieback, Restricted root area			Remove dead branches		Restricted and contained root system beginning to stress tree. Upper canopy manifesting symptoms of root confinement.		low	Yes	3yr Cycle	Low	Street	6/26/23
8	6299	Live oak	Lost Cove Drive	19	30	Good	Good	Negative									Yes	3yr Cycle	Low	Street	6/26/23
9		Laurel oak	South Bay Drive	35	65	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood > 10%, Dominant tree			Remove dead branches		Remove dead branches overhanging tennis court.		Urgent	Yes	3yr Cycle	High	Street	6/26/23
10		Laurel oak	Lost Cove Drive	26	55	Good	Fair	Negative	Co-dominant leaders w/bark inclusion	Bacteria, Other (see Notes 1 below)	Other (see Notes 1 below)	Priority 2 Prune, End weight reduction		Slime Flux wet weeping on trunk from bacterial infection. Not serious problem. The tree will likely outgrow the problem.		As soon as possible	Yes	3yr Cycle	High	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
11		Live oak	Lost Cove Drive	19.85	25	Poor	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Sparse foliage, Chlorotic, Epicormic sprouts		Phytotoxicity			Foliar symptoms consistent with herbicide damage	Leaf rollers present, appear to be taking advantage of weakened tree		Yes	3yr Cycle	Low	Street	6/26/23
12		Live oak	Lost Cove Drive	11	25	Poor	Good	Negative	Deadwood < 10%, Sparse foliage, Chlorotic, Epicormic sprouts		Phytotoxicity			Foliar symptoms consistent with herbicide damage	Leaf rollers present, appear to be taking advantage of weakened tree		Yes	3yr Cycle	Low	Street	6/26/23
13		Laurel oak	Lost Cove Drive	29	45	Fair	Good	Negative	Deadwood > 10%, Branch tip dieback	Other (see Notes 1 below)				Mistletoe infestation present in upper central canopy			Yes	3yr Cycle	Low	Street	6/26/23
14	2441	Live oak	Lost Cove Drive	28	45	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Root crown covered by soil or mulch			Large tree routine prune, End weight reduction				low	Yes	3yr Cycle	High	Street	6/26/23
15		Southern magnolia	Dawberry Court	12	20	Fair	Good	Negative	Sparse foliage, Chlorotic, Branch tip dieback, Restricted root area			Remove dead branches		Tree beginning to manifest symptoms associated with confined in restricted root system.	Sprouts around the roots are being improperly and dangerously managed with herbicides.		Yes	3yr Cycle	Low	Street	6/26/23
16		Live oak	Lost Cove Drive	29	45	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Root crown covered by soil or mulch			Large tree routine prune, End weight reduction				low	Yes	3yr Cycle	High	Street	6/26/23
17	2443	Live oak	Lost Cove Drive	28	45	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Cavity/decay - moderate			Large tree routine prune, End weight reduction				As soon as possible	Yes	3yr Cycle	High	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
18		Loquat tree	Shadow Box Court	8	15	Good	Good	Negative									Yes	3yr Cycle	Low	Street	6/26/23
19		Live oak	Shadow Box Court	27	50	Good	Good	Negative	Co-dominant leaders w/o included bark, Cavity/decay - small, Sprawling crown			Clearance Prune		Clearance pruning recommended over Road		As soon as possible	Yes	3yr Cycle	Low	Street	6/26/23
20		Live oak	Shadow Box Court	32	50	Good	Good	Negative	Co-dominant leaders w/o included bark, Cavity/decay - small, Sprawling crown			Clearance Prune		Clearance pruning recommended over Road		As soon as possible	Yes	3yr Cycle	Low	Street	6/26/23
21	2444	Live oak	Lost Cove Drive	20	40	Good	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Root crown covered by soil or mulch			Priority 2 Prune, Remove dead branches				As soon as possible	Yes	3yr Cycle	High	Street	6/26/23
22		Laurel oak	Lost Cove Drive	34	55	Good	Fair	Positive	Cavity/decay - moderate, Internal column of decay - moderate , Dominant tree, Root crown covered by soil or mulch, Root crown obscured by plants					Variegated Asiatic jasmine should be removed from lower trunk	Canopy already relatively compact. END weight reduction not recommended at this time		Yes	3yr Cycle	Moderate	Street	6/26/23
23	2445	Laurel oak	Lost Cove Drive	27	50	Good	Poor	Negative	Deadwood < 10%, Cavity/decay - small	Fungus		Priority 1 Prune, Remove hanger, End weight reduction		Large fungal conk is visible but so far trunk and root flare are solid. Maybe a few more years before removal is necessary	Remove jasmine ground cover that can cover fungal activity and decay.	As soon as possible	Yes	Annually	High	Street	6/26/23
24		Laurel oak	Lost Cove Drive	27	55	Good	Good	Negative	Deadwood < 10%, Cavity/decay - small, Root crown covered by soil or mulch, Root crown obscured by plants					Variegated Asiatic jasmine should be removed from lower trunk			Yes	3yr Cycle	Moderate	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
25		Laurel oak	Lost Cove Drive	28	50	Good	Good	Negative	Deadwood < 10%, Cavity/decay - small, Dominant tree, Root crown covered by soil or mulch, Root crown obscured by plants			Clearance Prune		Variegated Asiatic jasmine should be removed from lower trunk	Vertical roadway clearance pruning recommended	As soon as possible	Yes	3yr Cycle	Moderate	Street	6/26/23
26	2446	Laurel oak	Lost Cove Drive	30	55	Good	Fair	Positive	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - moderate			Priority 2 Prune, End weight reduction, Remove dead branches		Even though there is a large cavity on the lower trunk, the spread of decay so far has been limited. There is no positive, sounding above, or below the large cavity.		As soon as possible	Yes	3yr Cycle	High	Street	6/26/23
27		Laurel oak	Lost Cove Drive	17	45	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Stem girdling root, Dominant tree, Root crown covered by soil or mulch, Root crown obscured by plants			Clearance Prune		Variegated Asiatic jasmine should be removed from lower trunk	Vertical roadway clearance pruning recommended	As soon as possible	Yes	3yr Cycle	Low	Street	6/26/23
28		Laurel oak	South Bay Drive	32	65	Good	Fair	Positive	Co-dominant leaders w/o included bark, Cavity/decay - small, Basal decay			Clearance Prune		Early stages of basal decay detected. Continue to monitor	Vertical roadway clearance pruning recommended	As soon as possible	Yes	3yr Cycle	Moderate	Street	6/26/23
29		Laurel oak	South Bay Drive	35	65	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Cavity/decay - small, Sprawling crown, Internal column of decay - small, Dominant tree			End weight reduction		END weight reduction recommended to reduce likelihood of failure at bark inclusion sites		As soon as possible	Yes	3yr Cycle	High	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree ID	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations-Characteristics	Observations-Biotic Pest	Observations-Abiotic	Tree Work-Pruning	Tree Work-Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
30		Laurel oak	Granada Boulevard	42	65	Good	Fair	Positive	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - moderate, Sprawling crown, Soil Weakness			Priority 2 Prune, End weight reduction		Canopy END weight reduction recommended on all lateral limbs to create more compact and stable canopy to places less load and leverage on decayed central trunk		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/26/23
31	6289	Laurel oak	South Bay Drive	39	65	Fair	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Deadwood > 10%, Cavity/decay - small			Priority 2 Prune, End weight reduction, Remove dead branches				As soon as possible	Yes		High	Park	6/26/23
32		Laurel oak	Lost Cove Court	39	60	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Cavity/decay - moderate, Sprawling crown, Dominant tree			Priority 2 Prune, End weight reduction		Canopy END weight reduction recommended to reduce load on Bark inclusion sites	Mistletoe infestation observed in central canopy	As soon as possible	Yes	3yr Cycle	High	Street	6/26/23
33		Common crapemyrtle	Lost Cove Drive	19.05	20	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Park	6/26/23
34		Baldcypress	Lost Cove Drive	26	40	Good	Excellent	Negative									Yes	3yr Cycle	Low	Park	6/26/23
35		Baldcypress	Lost Cove Drive	20	40	Good	Excellent	Negative									Yes	3yr Cycle	Low	Park	6/26/23
36	2456	Laurel oak	Lost Cove Court	35	50	Good	Fair	Positive	Co-dominant leaders w/o included bark, Cavity/decay - small, Dominant tree	Other (see Notes 1 below)				Small Areas of decay detected sporadically throughout lower central trunk	Reduction pruning appears to have already been performed. No further Pruning recommended at this time. Mistletoe infestation observed in upper central canopy		Yes	3yr Cycle	Moderate	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
37		Baldcypress	Lost Cove Drive	22	40	Good	Excellent	Negative									Yes	3yr Cycle	Low	Park	6/26/23
38	2453	Laurel oak	South Bay Drive	34	50	Good	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%			Remove dead branches					Yes	3yr Cycle	Moderate	Park	6/26/23
39		Laurel oak	Lost Cove Court	14		Good	Good	Negative				Remove dead branches		Broken hanging limb. Observed hanging over area away from targets. Remove if desired.			Yes	3yr Cycle	Low	Street	6/26/23
40	2451	Baldcypress	Lost Cove Court	22	40	Good	Excellent	Negative									Yes	3yr Cycle	Low	Park	6/26/23
41	2451	Baldcypress	Lost Cove Court	22	40	Good	Excellent	Negative									Yes	3yr Cycle	Low	Park	6/26/23
42		Baldcypress	Lost Cove Court	18	35	Good	Excellent	Negative									Yes	3yr Cycle	Low	Park	6/26/23
43		Live oak	Lost Cove Court	6	20	Good	Good	Negative	Cavity/decay - moderate					Large wound on lower trunk. Appears To be compartmentalizing well			Yes	3yr Cycle	Low	Street	6/26/23
44		Baldcypress	Lost Cove Court	15	30	Good	Excellent	Negative									Yes	3yr Cycle	Low	Park	6/26/23
45	2460	Red maple	Lost Cove Court	34	40	Good	Fair	Negative	Co-dominant leaders w/bark inclusion			Large tree routine prune, End weight reduction				low	Yes	3yr Cycle	Moderate	Park	6/26/23
46		Laurel oak	Lost Cove Court	34	55	Good	Fair	Positive	Co-dominant leaders w/o included bark, Cavity/decay - moderate, Sprawling crown, Dominant tree			Priority 2 Prune, End weight reduction		Significant decay detected on central trunk near old large branch removal cut location. Canopy END weight reduction recommended to reduce load on decayed central trunk.		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations-Characteristics	Observations-Biotic Pest	Observations-Abiotic	Tree Work-Pruning	Tree Work-Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
47		Laurel oak	Lost Cove Court	42	55	Good	Fair	Positive	Co-dominant leaders w/o included bark, Cavity/decay - moderate, Sprawling crown, Dominant tree			Priority 2 Prune, End weight reduction		Significant decay detected on central trunk. Canopy END weight reduction recommended to reduce load on decayed central trunk.		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/26/23
48	2461	Laurel oak	Lost Cove Court	35	65	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Cavity/decay - small			Large tree routine prune, End weight reduction, Remove dead branches				low	Yes	3yr Cycle	Moderate	Park	6/26/23
49	2447	Southern magnolia	South Bay Drive	20	30	Fair	Good	Negative	Deadwood < 10%, Cavity/decay - small, Sparse foliage, Chlorotic, Branch tip dieback, Restricted root area					Canopy manifesting symptoms related to constricted and confined root space			Yes	3yr Cycle	Low	Street	6/26/23
50	6211	Laurel oak	Bay Springs Drive	45	60	Fair	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown			Large tree routine prune, Restoration prune, End weight reduction, Remove dead branches				low	Yes	3yr Cycle	Moderate	Park	6/26/23
51	6264	Laurel oak	Lost Cove Court	40	55	Fair	Poor	Positive	Co-dominant leaders w/o included bark, Deadwood > 10%, Cavity/decay - extensive, Basal decay, Sprawling crown, Sparse foliage, Branch tip dieback, Dominant tree			Priority 2 Removal		No good options for mitigation pruning. Tree is losing structural integrity. Removal recommended		Urgent	No		High	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree ID	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations-Characteristics	Observations-Biotic Pest	Observations-Abiotic	Tree Work-Pruning	Tree Work-Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
52		Laurel oak	Bay Springs Drive	45	65	Good	Fair	Positive	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Cavity/decay - moderate, Internal column of decay - small , Dominant tree					Small internal column of decay detected, canopy END weight reduction pruning has already been performed. Not recommended again at this time. Continue to monitor			Yes	3yr Cycle	Moderate	Street	6/26/23
53	6263	Laurel oak	Bay Springs Drive	30	65	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Deadwood < 10%, Cavity/decay - small, Sprawling crown			Priority 2 Prune, End weight reduction				As soon as possible	Yes	3yr Cycle	High	Park	6/26/23
54		Live oak	Bay Springs Drive	12	30	Good	Good	Negative	Co-dominant leaders w/o included bark			Structural prune				low	Yes	3yr Cycle	Low	Park	6/26/23
55		Laurel oak	Bay Springs Drive	35	65	Good	Fair	Negative	Co-dominant leaders w/o included bark, Cavity/decay - moderate, Sprawling crown, Dominant tree					Small to moderate amount of decay detected in central trunk. No recommended pruning at this time. Continue to monitor.			Yes	3yr Cycle	Low	Street	6/26/23
56		Laurel oak	Bay Springs Drive	41	70	Good	Poor	Positive	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - extensive, Basal decay, Sprawling crown, Dominant tree			Priority 2 Removal		Multiple significant structural defects and signs of canopy breakage/retrenchment	Trees in the state of structural decline. No good options for canopy medication pruning. Tree removal recommended	Urgent	No		Moderate	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
57		Live oak	South Bay Drive	31	65	Good	Good	Negative	Co-dominant leaders w/bark inclusion, Deadwood < 10%, Cavity/decay - small			Remove dead branches				As soon as possible	Yes	3yr Cycle	Moderate	Park	6/26/23
58	2464	Laurel oak	South Bay Drive	38	50	Fair	Poor	Positive	Co-dominant leaders w/o included bark, Cavity/decay - extensive, Basal decay, Sprawling crown, Branch tip dieback, Dominant tree			Priority 2 Removal				Urgent	No		High	Street	6/26/23
59		Live oak	Jonathan Manor Drive	48	55	Good	Good	Negative	Restricted root area, Root crown obscured by plants			Large tree routine prune, End weight reduction, Manage epicormic sprouts, Remove dead branches				low	Yes	3yr Cycle	Moderate	Street	6/26/23
60		Laurel oak	South Bay Drive	36	45	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Restricted root area			Priority 2 Prune, Restoration prune, End weight reduction				As soon as possible	Yes	Annually	High	Median	6/26/23
61		Laurel oak	South Park Place	19	20	Fair	Poor	Positive	Deadwood < 10%, Cavity/decay - extensive, Restricted root area			Priority 2 Removal		Tree beginning to manifest symptoms associated with confined in restricted root system. Extensive internal decay. Tree removal recommended		Urgent	No		High	Street	6/26/23
62		Live oak	Jonathan Manor Drive	31	60	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Moderate	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
63		Live oak	Jonathan Manor Drive	22	60	Good	Good	Negative	Co-dominant leaders w/o included bark, Restricted root area, Root crown obscured by plants								Yes	3yr Cycle	Moderate	Street	6/26/23
64		Live oak	Jonathan Manor Drive	27	55	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Root crown obscured by plants			Remove dead branches					Yes	3yr Cycle	Moderate	Street	6/26/23
65		Live oak	Jonathan Manor Drive	31	55	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%			Large tree routine prune, End weight reduction, Remove dead branches				low	Yes	3yr Cycle	Moderate	Street	6/26/23
66		Live oak	Jonathan Manor Drive	21	50	Good	Good	Negative	Deadwood < 10%, Root crown obscured by plants			Remove dead branches					Yes	3yr Cycle	Moderate	Street	6/26/23
67		Live oak	Jonathan Manor Drive	30	55	Good	Good	Negative	Deadwood < 10%			Priority 2 Prune, End weight reduction, Remove dead branches				As soon as possible	Yes	3yr Cycle	Moderate	Street	6/26/23
68		Live oak	Shawn Park Place	15	45	Good	Good	Negative									Yes	3yr Cycle	Low	Street	6/26/23
69		Live oak	Shawn Park Place	19	50	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Stem girdling root			Structural prune				As soon as possible	Yes	3yr Cycle	Moderate	Street	6/26/23
70		Laurel oak	Shawn Park Place	39	65	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - moderate	Bacteria, Other (see Notes 1 below)		Priority 2 Prune, End weight reduction		Slime flux bacterial bleeding from old pruning wounds		As soon as possible	Yes	3yr Cycle	High	Street	6/26/23
71		Laurel oak	Shawn Park Place	18	40	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Moderate	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
72		Laurel oak	Shawn Park Place	23	45	Good	Poor	Negative	Co-dominant leaders w/bark inclusion			End weight reduction		Subordination Reduction Pruning recommend it on Southern codominant leaders over the road to reduce load on bark inclusion sites		As soon as possible	Yes	3yr Cycle	Extreme	Street	6/26/23
73		Laurel oak	Shawn Park Place	21	45	Good	Good	Negative						Something appears to have stressed the tree metabolically last season. Tree is producing new vigorous asymptomatic growth. Continue to monitor			Yes	3yr Cycle	Moderate	Street	6/26/23
74		Southern magnolia	Shawn Park Place	9	25	Good	Good	Negative	Stem girdling root								Yes	3yr Cycle	Low	Street	6/26/23
75		Live oak	Shawn Park Place	28	35	Good	Good	Negative	Co-dominant leaders w/o included bark, Root crown obscured by plants								Yes	3yr Cycle	Moderate	Street	6/26/23
76	2471	Laurel oak	Shawn Park Place	27	65	Good	Good	Negative	Co-dominant leaders w/o included bark, Dominant tree								Yes	3yr Cycle	Moderate	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations-Characteristics	Observations-Biotic Pest	Observations-Abiotic	Tree Work-Pruning	Tree Work-Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
77	2472	Live oak	Shawn Park Place	28		Good	Good	Negative	Epicormic sprouts, Stem girdling root, Improperly Pruned - Overlifted/thinned			Clearance Prune		Selective removal of the low hanging sprouts to achieve 14 foot DOT required vertical clearance over roadway recommended. Do not remove Any other internal canopy sprouts. Encourage these to develop into large branches.		As soon as possible	Yes	3yr Cycle	Low	Street	6/26/23
78		Southern magnolia	Shawn Park Place	16	25	Fair	Good	Negative	Branch tip dieback								Yes	3yr Cycle	Low	Street	6/26/23
79		Live oak	South Bay Drive	19	45	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	6/26/23
80		Live oak	South Bay Drive	19	40	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	6/26/23
81		Live oak	South Bay Drive	35	45	Good	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Sprawling crown			End weight reduction		End weight reduction recommended on lower lateral limbs over the road with bark inclusion at Bass.		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/26/23
82		Live oak	Shawn Park Place	27	36	Fair	Good	Negative	Co-dominant leaders w/o included bark, Sparse foliage, Branch tip dieback								Yes	3yr Cycle	Low	Street	6/26/23
83		Laurel oak	South Bay Drive	36	60	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Deadwood < 10%, Root crown covered by soil or mulch			Priority 2 Prune, End weight reduction, Remove dead branches				As soon as possible	Yes	3yr Cycle	High	Park	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
84		Live oak	South Bay Drive	40	55	Good	Fair	Negative	Deadwood < 10%, Cavity/decay - small, Mechanical injury to trunk, branches - moderate		Mechanical Damage,	Clearance Prune, Remove dead branches		Car collision damaged part of lower trunk. Tree still OK.		As soon as possible	Yes	3yr Cycle	Moderate	Park	6/26/23
85		Live oak	Country Bay Court	27	50	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood > 10%, Sprawling crown, Root crown obscured by plants			Remove dead branches		Remove dead branches over Road		As soon as possible	Yes	3yr Cycle	High	Street	6/26/23
86		Live oak	Country Bay Court	29	50	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood > 10%, Sprawling crown, Root crown obscured by plants			Remove dead branches		Remove dead branches over tennis court and Road		As soon as possible	Yes	3yr Cycle	High	Street	6/26/23
87		Live oak	Country Bay Court	38	50	Good	Good	Negative	Co-dominant leaders w/o included bark, Sprawling crown, Root crown obscured by plants								Yes	3yr Cycle	Moderate	Street	6/26/23
88		Laurel oak	South Bay Drive	35	65	Good	Fair	Negative	Co-dominant leaders w/o included bark			Priority 2 Prune, End weight reduction				As soon as possible	Yes	3yr Cycle	Moderate	Park	6/26/23
89		Laurel oak	South Bay Drive	37	75	Good	Fair	Positive	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Internal column of decay - small, Dominant tree			Remove dead branches		Remove dead branches over parking lot		As soon as possible	Yes	3yr Cycle	High	Street	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree ID	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
90		Laurel oak	Gillette Court	37	70	Good	Fair	Positive	Co-dominant leaders w/o included bark, Deadwood > 10%, Cavity/decay - moderate, Sprawling crown, Improperly Pruned - stub cut, Internal column of decay - moderate			Priority 1 Prune, Remove hanger, End weight reduction		Large canopy tree directly over playground. End weight reduction recommended to create a more stable and compact canopy that places less load and leverage on decayed central trunk	Multiple dead branches and hangers over or near playground. Remove hangers and deadwood as soon as possible	Critical	Yes	3yr Cycle	Extreme	Street	6/26/23
91		Laurel oak	South Park Place	42	65	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Cavity/decay - moderate, Sprawling crown	Other (see Notes 1 below)		Large tree routine prune, End weight reduction		Tree has slime fix bacterial infection, not of much concern.		low	Yes	3yr Cycle	Moderate	Park	6/26/23
92		Laurel oak	South Bay Drive	46	65	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Cavity/decay - moderate, Sprawling crown	Other (see Notes 1 below)		Large tree routine prune, End weight reduction		Tree has slime fix bacterial infection, not of much concern.		low	Yes	3yr Cycle	Moderate	Park	6/26/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
93		Laurel oak	South Bay Drive	38		Good	Fair	Positive	Co-dominant leaders w/o included bark, Deadwood > 10%, Cavity/decay - moderate, Sprawling crown, Dominant tree			Priority 2 Prune, End weight reduction, Remove dead branches		Significant decay detected in lower central trunk. Multiple areas of decay throughout upper canopy branches. Large sprawling canopy overhanging walkway and near playground. END weight reduction recommended to create more compact stable canopy that places less load on decayed areas		Urgent	Yes	3yr Cycle	Moderate	Street	6/27/23
94		Live oak	South Bay Drive	18	40	Good	Good	Negative	Co-dominant leaders w/o included bark, Root crown covered by soil or mulch, Root crown obscured by plants								Yes	3yr Cycle	Low	Street	6/27/23
95		Laurel oak	South Bay Drive	38	70	Good	Good	Negative	Co-dominant leaders w/o included bark, Sprawling crown, Dominant tree					Large tree has already had one round of END weight reduction pruning. at this time			Yes	3yr Cycle	Moderate	Street	6/27/23
96		Laurel oak	South Bay Drive	28	70	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree			Priority 2 Prune, End weight reduction		Largest lateral limb with significant decay overhanging tennis court. End weight reduction recommended on Long lateral limb overhanging tennis court		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
97		Live oak	South Bay Drive	18	30	Good	Fair	Negative	Co-dominant leaders w/bark inclusion			Structural prune				low	Yes	3yr Cycle	Low	Park	6/27/23
98		Southern magnolia	South Bay Drive	8	20	Good	Good	Negative									Yes	3yr Cycle	Low	Street	6/27/23
99		Laurel oak	South Bay Drive	14	40	Good	Good	Negative									Yes	3yr Cycle	Moderate	Park	6/27/23
100		Laurel oak	South Bay Drive	32		Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Sprawling crown, Dominant tree			Remove dead branches		Remove dead branches		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
101		Laurel oak	South Bay Drive	12	40	Good	Good	Negative	Deadwood > 10%			Remove dead branches		Dead branch removal recommended		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
102		Sweetgum	South Bay Drive	27	55	Good	Good	Negative	Cavity/decay - small			Structural prune				low	Yes	3yr Cycle	Low	Street	6/27/23
103		Laurel oak	South Bay Drive	30.3	45	Good	Good	Negative				Priority 2 Prune		Dense Cluster of five trees. Overall trees are in very good shape, not overgrown very few health or structural defects. However Removal is recommended of western most leader, due to extensive decay from previous branch rubbing. See images. Overall risk rating will be greatly reduced after	Clearance pruning recommended over walkway	As soon as possible	Yes	3yr Cycle	High	Street	6/27/23
104		Sweetgum	South Bay Drive	33	65	Good	Good	Negative				Structural prune, End weight reduction				low	Yes	3yr Cycle	Moderate	Street	6/27/23
105		Live oak	South Bay Drive	44		Good	Good	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark					Repair lifted sidewalk - urgent		Urgent	Yes		Moderate	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree ID	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations-Characteristics	Observations-Biotic Pest	Observations-Abiotic	Tree Work-Pruning	Tree Work-Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
106	6397	Live oak	South Bay Drive	30	50	Good	Good	Negative	Deadwood < 10%, Sprawling crown, Dominant tree			Remove dead branches		Long and low branches growing over retention swale are not a structural problem.	Only pruning recommended is removal of small dead branches over walkway	low	Yes	3yr Cycle	Low	Street	6/27/23
107		Live oak	South Bay Drive	40	55	Good	Good	Negative	Deadwood < 10%, Sprawling crown, Dominant tree			Remove dead branches			Only pruning recommended is removal of small dead branches over walkway	low	Yes	3yr Cycle	Moderate	Street	6/27/23
108		Live oak	South Bay Drive	38	60	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Sprawling crown, Dominant tree			Remove dead branches		Remove dead branches over walkway		As soon as possible	Yes	3yr Cycle	High	Street	6/27/23
109		Live oak	South Bay Drive	12	25	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	6/27/23
110		Live oak	South Bay Drive	12	30	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	6/27/23
111		Live oak	South Bay Drive	11	30	Good	Good	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	6/27/23
112		Goldenra in tree	South Bay Drive	21.93	25	Good	Fair	Negative						Invasive species			Yes	3yr Cycle	Low	Street	6/27/23
113		Live oak	South Bay Drive	31	45	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Sprawling crown, Dominant tree			Remove dead branches		Remove dead branches over walkway		As soon as possible	Yes	3yr Cycle	High	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree ID	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations-Characteristics	Observations-Biotic Pest	Observations-Abiotic	Tree Work-Pruning	Tree Work-Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
114		Sweetgum	South Bay Drive	29	65	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree			Priority 2 Prune, Structural prune		Multiple codominant leaders on large growing relatively weak wooded tree. Subordination pruning recommended to establish central dominant lead and create better structure		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
115		Sweetgum	Bay Point Drive	36	65	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark								Yes	3yr Cycle	Moderate	Street	6/27/23
116		Live oak	Bay Point Drive	45	70	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Dominant tree			Remove dead branches		Remove small dead branches over walkway		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
117		Sweetgum	Bay Point Drive	32	65	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Moderate	Street	6/27/23
118		Live oak	Bay Point Drive	39	70	Good	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Dominant tree			Remove dead branches		Remove large dead hanging branches over walkway		Critical	Yes	3yr Cycle	High	Street	6/27/23
119		Sweetgum	Bay Point Drive	27	65	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Moderate	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree ID	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations-Characteristics	Observations-Biotic Pest	Observations-Abiotic	Tree Work-Pruning	Tree Work-Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
120	2986	Sweetgum	Granada Boulevard	38	70	Good	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree			Priority 2 Prune, Structural prune		Multiple codominant leaders on large growing relatively weak wooded tree. Subordination pruning recommended to establish central dominant lead and create better structure		As soon as possible	Yes	3yr Cycle	Low	Street	6/27/23
121		Sweetgum	Bay Point Drive	34	65	Good	Good	Negative	Co-dominant leaders w/o included bark, Cavity/decay - small								Yes	3yr Cycle	Moderate	Street	6/27/23
122		Sweetgum	South Bay Drive	34	70	Good	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree			Priority 2 Prune, Structural prune		Multiple codominant leaders on large growing relatively weak wooded tree. Subordination pruning recommended to establish central dominant lead and create better structure		As soon as possible	Yes	3yr Cycle	Low	Street	6/27/23
123		Live oak	South Bay Drive	55		Good	Good	Negative				Structural prune				low	Yes	3yr Cycle	Moderate	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations-Characteristics	Observations-Biotic Pest	Observations-Abiotic	Tree Work-Pruning	Tree Work-Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
124		Sweetgum	Cypress Cove Drive	33	70	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree			Priority 2 Prune, Structural prune		Multiple codominant leaders on large growing relatively weak wooded tree. Subordination pruning recommended to establish central dominant lead and create better structure		As soon as possible	Yes	3yr Cycle	Low	Street	6/27/23
125		Sweetgum	South Bay Drive	27	65	Good	Good	Negative									Yes	3yr Cycle	Moderate	Street	6/27/23
126		Sweetgum	Cypress Cove Drive	33	70	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree			Priority 2 Prune, Structural prune		Multiple codominant leaders on large growing relatively weak wooded tree. Structural subordination pruning recommended to establish central dominant lead and create better structure	Large dead branch over retention swale. Not over to sidewalk. Remove if desired.	As soon as possible	Yes	3yr Cycle	Low	Street	6/27/23
127		Sweetgum	Cypress Cove Drive	29	70	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree			Priority 2 Prune, Structural prune		Multiple codominant leaders on large growing relatively weak wooded tree. Subordination pruning recommended to establish central dominant lead and create better structure	.	As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
128		Live oak	South Bay Drive	34	60	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small			Remove dead branches				As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
129		Sweetgum	South Bay Drive	34	65	Good	Good	Negative				Structural prune				low	Yes	3yr Cycle	Moderate	Street	6/27/23
130		Sweetgum	Cypress Cove Drive	38	70	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree			Priority 2 Prune, Structural prune		Multiple codominant leaders on large growing relatively weak wooded tree. Subordination pruning recommended to establish central dominant lead and create better structure		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
131		Sweetgum	South Bay Drive	41	65	Good	Fair	Negative				Structural prune				low	Yes	3yr Cycle	Moderate	Street	6/27/23
132		Laurel oak	Cypress Cove Drive	41	75	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree			Remove dead branches		Remove dead branches over Road			Yes	3yr Cycle	High	Street	6/27/23
133	2983	Laurel oak	Cypress Cove Drive	32	65	Good	Good	Positive	Deadwood < 10%, Cavity/decay - small, Internal column of decay - small			Remove dead branches		Remove dead branches over Road		As soon as possible	Yes	3yr Cycle	High	Street	6/27/23
134		Laurel oak	South Bay Drive	34	60	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - moderate			Remove dead branches		Remove dead branches over Road		As soon as possible	Yes	3yr Cycle	High	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
135	6422	Live oak	Cypress Cove Drive	38	70	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree			Remove dead branches		Remove dead branches over Road			Yes	3yr Cycle	High	Street	6/27/23
136		Laurel oak	Cypress Cove Drive	26	65	Good	Fair	Negative	Co-dominant leaders w/o included bark, Root crown obscured by plants			Structural prune, End weight reduction				low	Yes	3yr Cycle	Moderate	Street	6/27/23
137		Laurel oak	South Bay Drive	24	60	Good	Good	Negative	Deadwood < 10%			Remove dead branches		Remove dead branches		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
138		Laurel oak	South Bay Drive	31	60	Good	Good	Negative	Co-dominant leaders w/o included bark							As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
139		Laurel oak	South Bay Drive	30	60	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Moderate	Street	6/27/23
140		Drake Chinese elm	South Bay Drive	19	30	Good	Good	Negative						Cut the stem girdling roots			Yes	3yr Cycle	Low	Park	6/27/23
141		Laurel oak	South Bay Drive	30	65	Good	Good	Negative	Dominant tree								Yes	3yr Cycle	Moderate	Street	6/27/23
142		Laurel oak	South Bay Drive	36	60	Good	Good	Negative	Deadwood < 10%, Dominant tree			Remove dead branches				As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
143		Laurel oak	South Bay Drive	32	60	Good	Good	Negative	Deadwood > 10%, Dominant tree			Remove dead branches				As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
144		Live oak	Ridge Pine Trail	32	60	Good	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood > 10%, Cavity/decay - moderate, Sprawling crown, Crack - vertical (torsion), Dominant tree			Priority 2 Prune, End weight reduction		Significant decay detected and observed on lower trunk. Canopy END weight reduction recommended to reduce the load and leverage on decayed central trunk		Urgent	Yes	3yr Cycle	High	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
145	2995	Laurel oak	South Park Place	49	70	Good	Good	Positive	Co-dominant leaders w/bark inclusion, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree			Priority 2 Prune, End weight reduction		End weight reduction recommended to reduce load on Central decayed trunk		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
146		Camphor tree	Summer Ridge Place	14	25	Fair	Fair	Negative				Priority 3 Removal		Invasive tree in an overgrown cluster including other invasive like goldenrain tree and Brazilian pepper.		low	No		Low	Street	6/27/23
147		Laurel oak	Summer Ridge Place	26	60	Good	Good	Negative	Deadwood < 10%			Remove dead branches		Remove dead branches over sidewalk		Urgent	Yes	3yr Cycle	High	Street	6/27/23
148		Laurel oak	Summer Ridge Place	16	45	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	6/27/23
149		Camphor tree	Summer Ridge Place	19.72	25	Fair	Fair	Negative				Priority 3 Removal		Invasive tree in an overgrown cluster including other invasive like goldenrain tree and Brazilian pepper.		low	No		Low	Street	6/27/23
150		Southern magnolia	Summer Ridge Place	9	40	Good	Excellent	Negative									Yes	3yr Cycle	Low	Street	6/27/23
151		Carolina laurelcherry	Chianti Drive	15	30	Good	Fair	Negative	Cavity/decay - moderate					Significant decay in upper canopy branches, however tree is small and not near targets. Mitigation pruning not necessary.			Yes	3yr Cycle	Low	Street	6/27/23
152		Southern magnolia	Summer Ridge Place	9	40	Good	Excellent	Negative									Yes	3yr Cycle	Low	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
153		Laurel oak	Chianti Drive	26	55	Poor	Good	Negative	Co-dominant leaders w/o included bark, Sparse foliage, Branch tip dieback					Severe canopy die back. Less than 50% live canopy remaining. No obvious signs of stressors, such as disease, pests, or environmental issues. Possibly lightning strike. Continue to monitor tree, may require removal in the next year or two.	Tree is currently set back from walking path. Not an immediate danger as limbs will likely fall straight down while away from sidewalk.		Yes	3yr Cycle	Low	Street	6/27/23
154		Laurel oak	Summer Ridge Place	14	40	Good	Good	Negative	Deadwood < 10%, Leaning trunk - stable lean			Remove dead branches		Remove dead branches		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
155		Laurel oak	Summer Ridge Place	14	35	Good	Good	Negative	Deadwood < 10%								Yes	3yr Cycle	Low	Street	6/27/23
156		Mimosa	Summer Ridge Place	14	45	Good	Good	Negative	Deadwood < 10%					Invasive tree. Consider removal			Yes	3yr Cycle	Low	Street	6/27/23
157		Carolina laurelcherry	Summer Ridge Place	11	30	Good	Good	Negative	Cavity/decay - moderate					Significant decay in upper canopy, can, but however tree is small. With compact stable canopy			Yes	3yr Cycle	Moderate	Street	6/27/23
158		Live oak	Summer Ridge Place	10	30	Good	Fair	Negative									Yes	3yr Cycle	Moderate	Street	6/27/23
159		Laurel oak	South Bay Drive	12	40	Good	Good	Negative									Yes	3yr Cycle	Moderate	Street	6/27/23
160		Laurel oak	Granada Boulevard	16	45	Good	Good	Negative	Deadwood < 10%								Yes	3yr Cycle	Low	Street	6/27/23
161		Laurel oak	Granada Boulevard	57	65	Good	Fair	Negative	Co-dominant leaders w/o included bark, Cavity/decay - moderate			Priority 2 Prune, Remove hanger, End weight reduction				Urgent	Yes	3yr Cycle	Moderate	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
162		Live oak	Summer Ridge Place	52	65	Good	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Stem girdling root			Remove dead branches				As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
163		Laurel oak	South Bay Drive	23	45	Good	Fair	Inconclusive	Cavity/decay - moderate								Yes	Annually	Moderate	Street	6/27/23
164	6327	Laurel oak	South Bay Drive	50	75	Good	Good	Negative				Remove dead branches		Large tree with Relatively compact for its size. Reduction printing not recommended at this time. Large removal cut wound at the base of trunk, appears to have compartmentalized well	Remove large dead branches over walkway.	As soon as possible	Yes	3yr Cycle	High	Street	6/27/23
165		Live oak	South Bay Drive	16	50	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Moderate	Street	6/27/23
166		Laurel oak	South Bay Drive	24	60	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark								Yes	3yr Cycle	Moderate	Street	6/27/23
167		Laurel oak	South Bay Drive	9	45	Good	Fair	Negative	Deadwood < 10%, Mechanical injury to trunk, branches - moderate		Other (see Notes 1 below)	Remove hanger		Large gash in lower trunk. Remove hanger.		As soon as possible	Yes	3yr Cycle	Low	Street	6/27/23
168		Laurel oak	South Bay Drive	9	45	Good	Fair	Negative	Deadwood < 10%, Mechanical injury to trunk, branches - moderate		Other (see Notes 1 below)						Yes	3yr Cycle	Low	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
169		Laurel oak	South Bay Drive	42	75	Good	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - moderate, Sprawling crown, Dominant tree			Priority 2 Prune, End weight reduction		Multiple areas of significant decay in upper and central canopy. END weight reduction recommended to reduce load on decayed areas		As soon as possible	Yes	3yr Cycle	Moderate	Street	6/27/23
170		Laurel oak	South Bay Drive	14	60	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Moderate	Street	6/27/23
171		Laurel oak	Southwind Court	21	60	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small			Remove dead branches		Remove dead branches over walkway		As soon as possible	Yes	3yr Cycle	High	Street	6/27/23
172	2885	Laurel oak	Granada Boulevard	32.65	55	Good	Fair	Negative	Co-dominant leaders w/bark inclusion					Canopy is still relatively small and compact. reduction pruning not recommended at this time			Yes	3yr Cycle	Moderate	Street	6/27/23
173	2886	Laurel oak	Granada Boulevard	13	35	Good	Good	Negative									Yes	3yr Cycle	Low	Street	6/27/23
174	2887	Tabebuia	South Bay Drive	17	45	Good	Fair	Negative	Co-dominant leaders w/bark inclusion					Relatively small and compact canopy. Reduction pruning not recommended at this time			Yes	3yr Cycle	Low	Street	6/27/23
175		Laurel oak	South Bay Drive	14	40	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	6/27/23
176	2889	Water oak	South Bay Drive	12	45	Good	Good	Negative									Yes	3yr Cycle	Low	Street	6/27/23
177	2890	Tabebuia	South Bay Drive	9	35	Good	Fair	Negative	Cavity/decay - moderate			Priority 2 Removal		Significant decay along Central trunk and upper canopy. No good options for mitigation. Remove tree		Urgent	No		High	Street	6/27/23
178		Tabebuia	South Bay Drive	15	30	Good	Good	Inconclusive	Co-dominant leaders w/bark inclusion								Yes	3yr Cycle	Moderate	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
179		Laurel oak	Lost Cove Court	49	75	Good	Good	Inconclusive	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sprawling crown, Dominant tree					Canopy reduction pruning not necessary at this time. Continue to monitor, may be recommended in the coming years			Yes	3yr Cycle	Moderate	Street	6/27/23
180		Laurel oak	Lost Cove Court	43	75	Good	Fair	Positive	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - moderate, Sprawling crown, Internal column of decay - moderate, Dominant tree			Priority 2 Prune		Multiple of large dead branches and weak unions throughout canopy. END weight reduction recommended as well as deadwood removal.		Urgent	Yes	3yr Cycle	High	Street	6/27/23
181		Live oak	Southwind Court	20	55	Good	Good	Negative	Deadwood > 10%			Remove dead branches		Remove dead branches over walkway		As soon as possible	Yes	3yr Cycle	High	Street	6/27/23
182		Laurel oak	Southwind Court	8	30	Good	Good	Negative	Leaning trunk - stable lean								Yes	3yr Cycle	Low	Street	6/27/23
183		Laurel oak	Southwind Court	17	60	Good	Good	Negative									Yes	3yr Cycle	Moderate	Street	6/27/23
184		Laurel oak	Southwind Court	16	50	Good	Good	Negative	Deadwood < 10%			Remove dead branches		Remove dead branches over walkway		As soon as possible	Yes	3yr Cycle	High	Street	6/27/23
185	6316	Laurel oak	Southwind Court	12		Good	Good	Negative									Yes	3yr Cycle	Low	Street	6/27/23
186		Laurel oak	Southwind Court	14	60	Good	Good	Negative									Yes	3yr Cycle	Moderate	Street	6/27/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
187		Southern magnolia	Summer Ridge Place	36	60	Good	Fair	Positive	Co-dominant leaders w/bark inclusion, Cavity/decay - extensive, Dominant tree			Priority 2 Prune, End weight reduction		Extensive decay on central trunk at bark inclusion site. Subordination, vertical reduction pruning recommended on north codominant leader w decay at base.		As soon as possible	Yes	3yr Cycle	High	Street	7/31/23
188	2996	Southern magnolia	South Park Place	12	40	Good	Good	Negative	Mechanical injury to trunk, branches - minor (abiotic)								Yes	3yr Cycle	Low	Park	7/31/23
189		Live oak	Summer Ridge Place	21	45	Good	Fair	Negative	Co-dominant leaders w/bark inclusion								Yes	3yr Cycle	Low	Park	7/31/23
190		Southern magnolia	South Park Place	10	30	Good	Good	Negative	Co-dominant leaders w/bark inclusion			Structural prune		Good structure except for a small codom w included bark 5 ft above ground on path side.. remove before this branch becomes a problem		low	Yes	3yr Cycle	Low	Park	7/31/23
191		Live oak	Summer Ridge Place	16	35	Good	Fair	Negative	Co-dominant leaders w/bark inclusion			Structural prune				As soon as possible	Yes	3yr Cycle	Moderate	Street	7/31/23
192		Drake Chinese elm	South Park Place	8	30	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Included Bark			Structural prune				As soon as possible	Yes	3yr Cycle	Low	Park	7/31/23
193		Laurel oak	Summer Ridge Place	27	65	Good	Good	Negative	Co-dominant leaders w/o included bark, Dominant tree								Yes	3yr Cycle	Moderate	Street	7/31/23
194		Live oak	South Park Place	15	45	Good	Good	Negative									Yes	3yr Cycle	Low	Street	7/31/23
195		Slash pine	Summer Ridge Place	8	15	Dead	Poor	Inconclusive				Priority 1 Removal		Dead tree overhanging sidewalk. Remove Remaining portions central trunk		Urgent	No		Extreme	Street	7/31/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
196		Slash pine	Summer Ridge Place	10	60	Good	Good	Inconclusive						Assessment of lower trunk not possible due to dense landscaping			Yes	3yr Cycle	Low	Street	7/31/23
197		Slash pine	Summer Ridge Place	10	60	Good	Good	Inconclusive						Assessment of lower trunk not possible due to dense landscaping. Consequently Unable to determine if slight lean is stable or unstable.			Yes	3yr Cycle	Low	Street	7/31/23
198		Laurel oak	South Park Place	42	65	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%			Remove dead branches				low	Yes	3yr Cycle	Low	Street	7/31/23
199		Southern magnolia	South Bay Drive	12		Good	Good	Negative									Yes	3yr Cycle	Low	Street	7/31/23
200		Laurel oak	South Bay Drive	37	65	Good	Fair	Negative	Excessive vine growth - (Biotic)	Vines, Other (see Notes 1 below)	Other (see Notes 1 below)	Priority 2 Prune, Structural prune		Slime Flux bacterial disease. Temporary and not serious. Excessive vines increase wind load on tree.		As soon as possible	Yes	3yr Cycle	High	Park	7/31/23
201		Drake Chinese elm	South Bay Drive	10		Good	Good	Negative	Co-dominant leaders w/o included bark			Clearance Prune					Yes	3yr Cycle	Low	Street	7/31/23
202		Laurel oak	South Bay Drive	35	65	Good	Fair	Positive	Co-dominant leaders w/bark inclusion, Cavity/decay - moderate, Internal column of decay - small , Dominant tree	Fungus		Priority 2 Prune, End weight reduction		No significant signs of health decline observed. Continue to monitor for signs of health decline. Pathogenic with decay fungus identified at northern trunk flare.	Canopy reduction of lateral codominant leader overhanging home with Bark inclusion	As soon as possible	Yes	3yr Cycle	Moderate	Street	7/31/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
203		Southern magnolia	South Bay Drive	25	45	Good	Good	Negative	Co-dominant leaders w/bark inclusion, Deadwood < 10%, Cavity/decay - small, Dominant tree			Clearance Prune		Tree relatively compact and stable. Only minor clearance pruning over sidewalk recommended at this time		low	Yes	3yr Cycle	Low	Street	7/31/23
204	6452	Laurel oak	Country Bay Court	28	55	Fair	Fair	Positive	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small, Sparse foliage, Branch tip dieback, Restricted root area, Internal column of decay - small, Root crown covered by soil or mulch			Remove dead branches		She appears to be suffering from restricted reading area and too much soil over planting on top of trunk flare.	Root crown excavation recommended, continue to monitor for signs of health decline	As soon as possible	Yes	3yr Cycle	Moderate	Street	7/31/23
205		Laurel oak	Hidden Bay Lane	29	45	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Cavity/decay - small			Priority 2 Prune, Structural prune, End weight reduction				Urgent	Yes	3yr Cycle	High	Street	7/31/23
206		Southern magnolia	Cypress Cove Drive	10	20	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Park	7/31/23
207	2901	Laurel oak	Hidden Bay Lane	13	40	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Cavity/decay - small								Yes	3yr Cycle	Low	Street	7/31/23
208	6226	Southern magnolia	Cypress Cove Drive	15	35	Good	Good	Negative				Clearance Prune, Manage epicormic sprouts				As soon as possible	Yes	3yr Cycle	Low	Park	7/31/23
209	6228	Goldenra in tree	Hidden Bay Lane	29	45	Good	Good	Negative	Co-dominant leaders w/o included bark, Dominant tree								Yes	3yr Cycle	Low	Street	7/31/23
210		Common crapemyrtle	Cypress Cove Drive	14	18	Good	Fair	Negative	Cavity/decay - moderate, Improperly Pruned - Topped								Yes	3yr Cycle	Low	Park	7/31/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
211		Laurel oak	Cypress Cove Drive	27	55	Good	Fair	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%			Remove dead branches		Remove Large dead branches over backyard.		As soon as possible	Yes	3yr Cycle	High	Street	7/31/23
212	6229	Laurel oak	Hidden Bay Lane	37	60	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Deadwood < 10%, Cavity/decay - small, Dominant tree			Priority 2 Prune, End weight reduction		Canopy END weight reduction recommended on Southern lateral codominant leader with bark inclusion at base		Urgent	Yes	3yr Cycle	Moderate	Street	7/31/23
213		American sycamore	Bay Point Drive	32	65	Fair	Good	Negative	Deadwood < 10%, Branch tip dieback, Epicormic sprouts, Restricted root area, Improperly Pruned - stub cut			Deadwood, Manage epicormic sprouts, Remove dead branches				As soon as possible	Yes	3yr Cycle	Low	Street	7/31/23
214		American sycamore	Bay Point Drive	30	70	Good	Good	Negative	Deadwood < 10%, Restricted root area, Improperly Pruned - stub cut			Remove dead branches				As soon as possible	Yes	3yr Cycle	Low	Park	7/31/23
215		Laurel oak	Hidden Bay Lane	27	65	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Cavity/decay - moderate, Cavity/decay - extensive			Priority 2 Prune, End weight reduction		Multiple of large bark inclusions and areas of significant decay from old pruning removal cuts throughout upper central canopy. Significant structural defects present, tree near multiple homes.	Either perform significant canopy reduction or remove tree	As soon as possible	Yes	3yr Cycle	High	Street	7/31/23
216		Laurel oak	Bay Hill Boulevard	22	55	Good	Good	Negative	Deadwood < 10%			Remove dead branches		Remove small dead branches over sidewalk			Yes	3yr Cycle	Moderate	Street	7/31/23
217		Goldenrain tree	Bay Hill Boulevard	19	60	Good	Good	Negative	Deadwood < 10%			Remove dead branches		Remove dead branches over		As soon as possible	Yes	3yr Cycle	Moderate	Street	7/31/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations-Characteristics	Observations-Biotic Pest	Observations-Abiotic	Tree Work-Pruning	Tree Work-Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
218		Tabebuia	Cypress Cove Drive	12	30	Fair	Good	Negative	Cavity/decay - moderate, Chlorotic					Lower trunk surrounded by dense landscaping. Unable to assess lower trunk.			Yes	3yr Cycle	Low	Street	7/31/23
219		American sycamore	Bay Hill Boulevard	26	65	Good	Good	Negative	Restricted root area, Improperly Pruned - stub cut								Yes	3yr Cycle	Low	Park	7/31/23
220		American sycamore	Bay Hill Boulevard	30	65	Fair	Good	Negative	Deadwood < 10%, Branch tip dieback, Restricted root area, Improperly Pruned - stub cut			Manage epicormic sprouts, Remove dead branches				As soon as possible	Yes	3yr Cycle	Low	Park	7/31/23
221		Carolina laurelcherry	Bay Hill Boulevard	12	30	Fair	Fair	Negative	Co-dominant leaders w/bark inclusion, Excessive vine growth - (Biotic)			Clearance Prune, Structural prune				low	Yes	3yr Cycle	Moderate	Park	8/1/23
222		Live oak	Bay Hill Boulevard	40.5	50	Good	Good	Negative	Deadwood > 10%, Cavity/decay - small			Remove dead branches		Cluster of 6 live oaks. All have good health and structure. Only minor deadwood removal recommended.		Urgent	Yes	3yr Cycle	High	Street	8/1/23
223		Live oak	Bay Hill Boulevard	17	35	Good	Good	Negative	Deadwood < 10%			Remove dead branches					Yes	3yr Cycle	Moderate	Street	8/1/23
224		Live oak	Bay Hill Boulevard	25.24	45	Good	Good	Negative				Remove dead branches		Cluster of seven live oaks, all have good health and structure. Only minor Deadwood Removal recommended hit this time. Do not continue to over lift and improperly thin the lower interior canopy		low	Yes	3yr Cycle	Low	Street	8/1/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
225		Live oak	Cypress Cove Drive	25	40	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark								Yes		Low	Park	8/1/23
226	2982	Baldcypress	Cypress Cove Drive	26	55	Good	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	8/1/23
227		Laurel oak	Hidden Bay Lane	16	50	Good	Good	Negative	Deadwood < 10%								Yes	3yr Cycle	Low	Street	8/1/23
228		Live oak	Hidden Bay Lane	16.97	40	Good	Good	Negative	Deadwood < 10%, Cavity/decay - small			Remove dead branches		Cluster of 3 live oaks.		As soon as possible	Yes	3yr Cycle	Low	Street	8/1/23
229		Goldenrain tree	Bay Hill Boulevard	18.68	50	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood > 10%			Priority 2 Prune, Remove dead branches		Remove dead branches near sidewalk		As soon as possible	Yes	3yr Cycle	Moderate	Street	8/1/23
230	2982	Baldcypress	Cypress Cove Drive	12.73	45	Good	Fair	Negative	Co-dominant leaders w/bark inclusion								Yes	3yr Cycle	Low	Street	8/1/23
231		Live oak	Hidden Bay Lane	10	30	Good	Good	Negative	Deadwood < 10%, Cavity/decay - small								Yes	3yr Cycle	Low	Street	8/1/23
232		Laurel oak	Cypress Cove Drive	51	55	Fair	Poor	Positive	Co-dominant leaders w/bark inclusion, Deadwood < 10%, Cavity/decay - extensive	Fungus		Priority 2 Removal		Most of west side is hollow above the ganoderma conks		Urgent	No		Moderate	Park	8/1/23
233	620(27)	Laurel oak	Cypress Cove Drive	45	55	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Co-dominant leaders w/o included bark, Deadwood < 10%, Sprawling crown			Deadwood, Remove dead branches				low	Yes	3yr Cycle	Low	Park	8/1/23
234		Laurel oak	Bentley Park Circle	47	55	Good	Poor	Positive	Co-dominant leaders w/bark inclusion, Deadwood < 10%, Cavity/decay - extensive, Sprawling crown			Priority 2 Removal		Lots of internal decay south side of trunk		Urgent	No		Moderate	Park	8/1/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
235		Southern magnolia	Cypress Cove Drive	20	40	Fair	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%, Sparse foliage, Branch tip dieback, Stem girdling root, Restricted root area			Priority 2 Prune	Remove stem girdling root(s)	Custom girdling root. Remove dead branches over Road		As soon as possible	Yes	3yr Cycle	Moderate	Street	8/1/23
236		Southern magnolia	Cypress Cove Drive	15	35	Fair	Good	Negative	Deadwood < 10%, Sparse foliage, Branch tip dieback, Restricted root area								Yes	3yr Cycle	Low	Street	8/1/23
237		Baldcypress	Bentley Park Circle	20	40	Excellent	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	8/1/23
238		Baldcypress	Bentley Park Circle	20	35	Excellent	Excellent	Negative									Yes	3yr Cycle	Low	Street	8/1/23
239		Baldcypress	Bentley Park Circle	21	35	Excellent	Good	Negative	Co-dominant leaders w/o included bark								Yes	3yr Cycle	Low	Street	8/1/23
240	2977	Live oak	Bentley Park Circle	28	55	Good	Good	Negative	Co-dominant leaders w/o included bark, Deadwood < 10%			Deadwood, Remove dead branches				As soon as possible	Yes	3yr Cycle	Low	Park	8/1/23
241		Baldcypress	Cypress Cove Drive	27	45	Good	Fair	Negative	Co-dominant leaders w/bark inclusion, Root crown obscured by plants								Yes	3yr Cycle	Low	Street	8/1/23
242	2976	Baldcypress	Cypress Cove Drive	21	30	Excellent	Excellent	Negative									Yes	3yr Cycle	Low	Street	8/1/23
243		Baldcypress	Cypress Cove Drive	20	45	Excellent	Excellent	Negative									Yes	3yr Cycle	Low	Street	8/1/23
244		Water Tupelo	Cypress Cove Drive	33	55	Good	Fair	Positive	Co-dominant leaders w/o included bark, Cavity/decay - moderate								Yes	3yr Cycle	Low	Park	8/1/23
245		Water Tupelo	Bentley Park Circle	60	50	Good	Fair	Inconclusive	Co-dominant leaders w/bark inclusion, Cavity/decay - moderate					Very large tupelo tree, surrounded by dense undergrowth vegetation preventing analysis or measurement of lower trunk.	Size and species likely makes this a protected tree. Should be investigated further by water management district officials		Yes	3yr Cycle	Low	Street	8/1/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B

South Bay - Tree Risk Assessment

August 21, 2023

Tree Id	Previous ID / Tag #	Species	Address Street	DBH	Tree Height (Estimated)	Health Condition	Structure Condition	Mallet Test (internal decay)	Observations- Characteristics	Observations- Biotic Pest	Observations- Abiotic	Tree Work- Pruning	Tree Work- Root/soil	Notes 1	Notes 2	Priority	Monitor	Cycle	Risk Rating	Land Type	Date Added
246	290(5)?	Laurel oak	Bay Hill Boulevard	48	65	Good	Poor	Positive	Co-dominant leaders w/bark inclusion, Cavity/decay - moderate, Sprawling crown, Infrastructure conflict, Poor branch taper, Dominant tree	Fungus		Priority 2 Removal		Large mature tree Near multiple homes, with significant structural defects and actively lifting electrical utility box. No good options for canopy mitigation without potentially killing the tree. Tree removal recommended	Pathogenic wood decay fungus observed in upper central canopy wound	Urgent	No		High	Street	8/1/23

Advanced Tree Care

Chuck Lippi - ISA Board Certified Master Arborist FL 0501B
 Danny Lippi - ISA Board Certified Master Arborist FL 61435B